

Your AutoCheck Vehicle History Report

Report run: 07/28/2020 14:50:07 EDT



This report is brought to you by:

TESCO

PO box 167230

Oregon, OH 43616

419.836.2835

www.tescobus.com

2012 Ford F550 Super Duty Regular Cab Chassis (6.7L V8 Diesel)

VIN: 1FDGF5GT6CEC78382

Class: Medium/Heavy Truck

Country of Assembly: United States

This vehicle is not eligible for Buyback Protection



Due to the vehicle's history showing major [state title brand\(s\)](#) and/or not meeting other Buyback Protection terms and conditions.

YOUR VEHICLE AT A GLANCE



The AutoCheck Score is based on a vehicle's history such as vehicle class and age, number of owners, accident and damage history, title brands, odometer readings etc. This score is used to compare vehicle's favorability against the entire market of vehicles with the same scoring system.

- ✓ No State Title Brand Reported
- ✓ No Accident Reported
No Air Bag Deployed
- ✓ No Other Damage Reported
- i Other Title Brand or Specific Event Reported
- ✓ No Odometer Problem(s) Reported
Last Odometer Reading: 67,238
- i Open Recall(s) Reported (5)
- i Service & Repair Information Reported



MULTIPLE OWNERS

Calculated Owners: **2**

Owner History



Last Owner


Purchased: 2012
Where: NY
Owned from: 11/29/2012 - 04/30/2018
5 year(s) 5 month(s)



Current Owner


Purchased: 2018
Where: OH
Owned from: 04/30/2018 - Present
2 year(s) 2 month(s)

Vehicle Usage

 **Vehicle Use:** There is indication of the below usage(s) for this vehicle
Personal | Fleet | Rental | Lease | Taxi | Livery | Police | Government | Drivers Ed | Commercial



Major State Title Brand Check

 **Your Vehicle Checks Out:** No major state title brand has been reported by the state Division of Motor Vehicles (DMV).



0 Problem(s) Reported

Major State Title Areas Checked



No fire brand



No hail brand



No flood brand



No junk or scrapped brand



No manufacturer buyback



No lemon brand



No salvage brand



No rebuilt or rebuildable brand



No odometer brand (EML or NAM)



Accident Check



Your Vehicle Checks Out: AutoCheck has not received any accident records from government sources and independent agencies on this vehicle. Not all accidents are reported to AutoCheck.



**NO ACCIDENT
FOUND ON RECORD**



Damage Check



Your Vehicle Checks Out: AutoCheck has not received a damage-related event from an auction or an independent source. Not all damage events are reported to AutoCheck. It is recommended to have pre-owned vehicles inspected by a third party prior to purchase.



**NO DAMAGE
FOUND ON RECORD**

0 Problem(s) Reported

Other Problem Areas Checked



No non-title fire damaged record



No non-title hail damaged record



No non-title flood damaged record



No auction junk or scrapped record



No auction rebuilt or rebuildable record



No salvage auction record



No damaged or major damage incident record



No structural damage or structural alteration record



No recycling facility record



No crash test record



Other Title Brand And Specific Event Check








Information Reported: One or more non-major state title brand(s) and/or additional significant event(s) has been reported to AutoCheck. It is recommended to have pre-owned vehicles inspected by a third party prior to purchase.

1 Event(s) Reported

Vehicle Events Checked



No Insurance Loss record

1 Event(s) Reported	Vehicle Events Checked
	No Titled to an insurance company record
	No Auction Lemon/Manufacturer Buyback record
	No abandoned title record
	No grey market title record
	Loan/Lien record(s)
	No repossessed record
	No corrected title record
	No duplicate title record
	No theft record(s)



Odometer Check



Your Vehicle Checks Out: No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.











State title odometer check










Auction odometer check



Odometer calculation check

0 Problem(s) Reported	Mileage	Date Reported
	99	12/20/2012
	31,885	10/07/2015
	36,308	01/11/2016
	40,038	03/14/2016
	44,131	07/11/2016
	48,683	11/21/2016
	49,547	12/13/2016
	50,572	02/17/2017
	50,823	02/22/2017

0 Problem(s) Reported	Mileage	Date Reported
	54,296	05/22/2017
	58,907	11/20/2017
	59,989	12/18/2017
	60,101	01/30/2018
	63,094	04/30/2018
	63,535	05/20/2019
	67,238	05/07/2020



Open Recall Check



Information Reported: AutoCheck found **5** recalls. It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Not all open recalls are reported to AutoCheck.

Recall Date	MFR Recall Number	Component
12/10/2015	15M02	Customer Satisfaction Program - Multi Repair: EXHAUST GAS TEMPERATURE SENSOR EXTENDED COVERAGE
08/28/2017	17M05	Customer Satisfaction Program - Multi Repair: EXHAUST MANIFOLD STUD REPLACEMENT
01/16/2018	18M01	Customer Satisfaction Program - Multi Repair: REDUCTANT HEATER AND SENDER ASSEMBLY REPAIR
07/25/2018	18M03	Customer Satisfaction Program - Multi Repair: CHARGE AIR COOLER OUTLET TUBE INSPECTION
03/27/2019	18M05	Customer Satisfaction Program - Multi Repair: TURBOCHARGER EXTENDED WARRANTY COVERAGE



Service And Repair History Check



Information Reported: There have been some service and repair information reported from dealers or service shops.

Date of Service	Location	Source	Service Type
08/11/2014	NY	Romano Ford VW 315.637.4491	AIR FILTER CHANGED EMISSION SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION RECOMMENDED MAINTENANCE PERFORMED

Date of Service	Location	Source	Service Type
08/21/2014	NY	Romano Ford VW 315.637.4491	STEERING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION
12/26/2014	NY	Romano Ford VW 315.637.4491	VEHICLE SERVICED
01/09/2015	NY	Romano Ford VW 315.637.4491	VEHICLE SERVICED
03/09/2015	NY	Romano Ford VW 315.637.4491	BATTERY SERVICED OR REPLACED MULTIPLE POINT VEHICLE INSPECTION RECOMMENDED MAINTENANCE PERFORMED BRAKES SERVICED ELECTRICAL SYSTEM SERVICED TIRES OR WHEELS SERVICE PERFORMED
07/14/2015	NY	Romano Ford VW 315.637.4491	VEHICLE SERVICED
10/07/2015	NY	Dealer Service	EXHAUST SYSTEM SERVICED VEHICLE SERVICED
01/11/2016	NY	Dealer Service	MULTIPLE POINT VEHICLE INSPECTION VEHICLE SERVICED
03/14/2016	NY	Dealer Service	FUEL SYSTEM SERVICED ENGINE SERVICED BRAKES SERVICED TIRES OR WHEELS SERVICE PERFORMED LUBE, OIL AND/OR FILTER CHANGED
07/11/2016	NY	Dealer Service	BATTERY SERVICED OR REPLACED MULTIPLE POINT VEHICLE INSPECTION VEHICLE INSPECTED BRAKES SERVICED TIRES OR WHEELS SERVICE PERFORMED VEHICLE SERVICED
11/21/2016	NY	Dealer Service	BRAKES SERVICED LUBE, OIL AND/OR FILTER CHANGED
12/13/2016	NY	Dealer Service	COOLING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION TIRES OR WHEELS SERVICE PERFORMED VEHICLE SERVICED
02/17/2017	NY	Dealer Service	EXHAUST SYSTEM SERVICED
02/22/2017	NY	Dealer Service	VEHICLE SERVICED
05/22/2017	NY	Dealer Service	COOLING SYSTEM SERVICED
11/20/2017	NY	Dealer Service	STEERING SYSTEM SERVICED FUEL SYSTEM SERVICED AIR CONDITIONING SERVICED BRAKES SERVICED LUBE, OIL AND/OR FILTER CHANGED

Date of Service	Location	Source	Service Type
			VEHICLE SERVICED
12/18/2017	NY	Dealer Service	MULTIPLE POINT VEHICLE INSPECTION ENGINE SERVICED WIPERS REPLACED AND/OR SERVICED EXHAUST SYSTEM SERVICED TIRES OR WHEELS SERVICE PERFORMED
01/30/2018	NY	Dealer Service	AIR CONDITIONING SERVICED
02/12/2018	NY	Romano Ford VW 315.637.4491	FUEL SYSTEM SERVICED BATTERY SERVICED OR REPLACED MULTIPLE POINT VEHICLE INSPECTION TIRES OR WHEELS SERVICE PERFORMED LUBE, OIL AND/OR FILTER CHANGED
03/02/2018	NY	Romano Ford VW 315.637.4491	FUEL SYSTEM SERVICED BATTERY SERVICED OR REPLACED MULTIPLE POINT VEHICLE INSPECTION TIRES OR WHEELS SERVICE PERFORMED LUBE, OIL AND/OR FILTER CHANGED

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order. Any discrepancies will be in bold text.

Report Run Date: 07/28/2020 14:50:07 EDT

Vehicle: 2012 Ford F550 Super Duty (1FDGF5GT6CEC78382)

Event Date	Location	Odometer Reading	Data Source	Details
09/14/2012			Independent Source	VEHICLE MANUFACTURED AND SHIPPED TO DEALER
12/20/2012	SYRACUSE, NY	99	Motor Vehicle Dept.	TITLE(Lien Reported)
01/28/2014	SYRACUSE, NY		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
08/11/2014	FAYETTEVILLE, NY		Romano Ford VW 315.637.4491	AIR FILTER CHANGED EMISSION SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION RECOMMENDED MAINTENANCE PERFORMED
08/21/2014	FAYETTEVILLE, NY		Romano Ford VW 315.637.4491	STEERING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION
12/26/2014	FAYETTEVILLE, NY		Romano Ford VW 315.637.4491	VEHICLE SERVICED
01/09/2015	FAYETTEVILLE, NY		Romano Ford VW 315.637.4491	VEHICLE SERVICED

Event Date	Location	Odometer Reading	Data Source	Details
01/12/2015	SYRACUSE, NY		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
03/09/2015	FAYETTEVILLE, NY		Romano Ford VW 315.637.4491	BATTERY SERVICED OR REPLACED MULTIPLE POINT VEHICLE INSPECTION RECOMMENDED MAINTENANCE PERFORMED BRAKES SERVICED ELECTRICAL SYSTEM SERVICED TIRES OR WHEELS SERVICE PERFORMED
07/14/2015	FAYETTEVILLE, NY		Romano Ford VW 315.637.4491	VEHICLE SERVICED
10/07/2015	ONEIDA, NY	31,885	Dealer Service	EXHAUST SYSTEM SERVICED VEHICLE SERVICED
12/10/2015			Manufacturer	MANUFACTURER RECALL RECALL 15M02 Customer Satisfaction Program - Multi Repair: EXHAUST GAS TEMPERATURE SENSOR EXTENDED COVERAGE LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR.
01/11/2016	ONEIDA, NY	36,308	Dealer Service	MULTIPLE POINT VEHICLE INSPECTION VEHICLE SERVICED
01/21/2016	SYRACUSE, NY		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
03/14/2016	ONEIDA, NY	40,038	Dealer Service	FUEL SYSTEM SERVICED ENGINE SERVICED BRAKES SERVICED TIRES OR WHEELS SERVICE PERFORMED LUBE, OIL AND/OR FILTER CHANGED
07/11/2016	ONEIDA, NY	44,131	Dealer Service	BATTERY SERVICED OR REPLACED MULTIPLE POINT VEHICLE INSPECTION VEHICLE INSPECTED BRAKES SERVICED TIRES OR WHEELS SERVICE PERFORMED VEHICLE SERVICED
11/21/2016	ONEIDA, NY	48,683	Dealer Service	BRAKES SERVICED LUBE, OIL AND/OR FILTER CHANGED
12/13/2016	ONEIDA, NY	49,547	Dealer Service	COOLING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION TIRES OR WHEELS SERVICE PERFORMED VEHICLE SERVICED
01/23/2017	SYRACUSE, NY		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
02/17/2017	ONEIDA, NY	50,572	Dealer Service	EXHAUST SYSTEM SERVICED

Event Date	Location	Odometer Reading	Data Source	Details
02/22/2017	ONEIDA, NY	50,823	Dealer Service	VEHICLE SERVICED
05/22/2017	ONEIDA, NY	54,296	Dealer Service	COOLING SYSTEM SERVICED
08/28/2017			Manufacturer	MANUFACTURER RECALL RECALL 17M05 Customer Satisfaction Program - Multi Repair: EXHAUST MANIFOLD STUD REPLACEMENT LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR.
11/20/2017	ONEIDA, NY	58,907	Dealer Service	STEERING SYSTEM SERVICED FUEL SYSTEM SERVICED AIR CONDITIONING SERVICED BRAKES SERVICED LUBE, OIL AND/OR FILTER CHANGED VEHICLE SERVICED
12/18/2017	ONEIDA, NY	59,989	Dealer Service	MULTIPLE POINT VEHICLE INSPECTION ENGINE SERVICED WIPERS REPLACED AND/OR SERVICED EXHAUST SYSTEM SERVICED TIRES OR WHEELS SERVICE PERFORMED
01/16/2018			Manufacturer	MANUFACTURER RECALL RECALL 18M01 Customer Satisfaction Program - Multi Repair: REDUCTANT HEATER AND SENDER ASSEMBLY REPAIR LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR.
01/30/2018	ONEIDA, NY	60,101	Dealer Service	AIR CONDITIONING SERVICED
02/12/2018	SYRACUSE, NY		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
02/12/2018	FAYETTEVILLE, NY		Romano Ford VW 315.637.4491	FUEL SYSTEM SERVICED BATTERY SERVICED OR REPLACED MULTIPLE POINT VEHICLE INSPECTION TIRES OR WHEELS SERVICE PERFORMED LUBE, OIL AND/OR FILTER CHANGED
03/02/2018	FAYETTEVILLE, NY		Romano Ford VW 315.637.4491	FUEL SYSTEM SERVICED BATTERY SERVICED OR REPLACED MULTIPLE POINT VEHICLE INSPECTION TIRES OR WHEELS SERVICE PERFORMED LUBE, OIL AND/OR FILTER CHANGED
04/30/2018	OREGON, OH	63,094	Motor Vehicle Dept.	TITLE(Title #:4805401595)
07/25/2018			Manufacturer	MANUFACTURER RECALL RECALL 18M03 Customer Satisfaction Program - Multi Repair: CHARGE AIR COOLER OUTLET TUBE INSPECTION LOCATE YOUR NEAREST AUTHORIZED

Event Date	Location	Odometer Reading	Data Source	Details
				FORD DEALER TO SCHEDULE REPAIR.
03/27/2019			Manufacturer	MANUFACTURER RECALL RECALL 18M05 Customer Satisfaction Program - Multi Repair: TURBOCHARGER EXTENDED WARRANTY COVERAGE LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR.
05/20/2019	OREGON, OH	63,535	Motor Vehicle Dept.	TITLE(Title #:4805643228)
05/24/2019	OREGON, OH		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
05/07/2020	OREGON, OH	67,238	Motor Vehicle Dept.	TITLE(Title #:4805839138)

This Vehicle's Glossary

Below are the specific definitions for events that appear in this vehicle's report. More information is available in the full [AutoCheck glossary](#).

Term	Section Location	Definition
Loan/Lien	Other Title Brand and Specific Event Check	A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.
Personal Use	Vehicle Use	This vehicle was driven for personal use.
Open Recall	History Section	A recall is considered 'open' for a vehicle when it has not received the required service to correct the identified recall. The vehicle will need to be taken to a repair center that has been authorized by the manufacturer to correct any open recall conditions.
Recall	History Section	A safety, emission or bulletin issued by the vehicle manufacturer, the Environmental Protection Agency (EPA) or the Department of Transportation (DOT). These are different than a service bulletin. A recall involves work that must be done at no charge to the consumer by an authorized dealer of the vehicle make involved.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 955 American Lane Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (1FDGF5GT6CEC78382) does not qualify for AutoCheck Buyback Protection.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.